


**X(04)07 Thinner Delineators on SR-118****PRODUCT/PROCESS**Category: **Signs**

Trade Name:

Manufacturer: **Jordan River Galvanizing**Web Site: [www.jrgalv.com](http://www.jrgalv.com)Local Distributor: **Jordan River Galvanizing**Web Site: [www.jrgalv.com](http://www.jrgalv.com)UDOT R-52 No.: **none****STATUS**Work Plan (5%): [See interim report](#)Construction Report (10%): [See interim report](#)Interim Report (25% ea.): [Complete](#)

Final Report (10%):

Total % Complete: **40%**

Notes:

**LOCATION**Reg./Dist.: **4/Richfield**Route: **SR-118**

Description:

Direction:

Beg. MP: **16**

Description:

End MP:

Description:

Structure No:

**CONTACTS**Champion: **Les Henrie**Research Primary: **Richard Sharp**Email: [rsharp@utah.gov](mailto:rsharp@utah.gov)Phone: **(801)965-4314**Research Secondary: **Ken Berg**Email: [kenberg@utah.gov](mailto:kenberg@utah.gov)Phone: **(801)965-4321****GENERAL**Maintenance Station(s): **4327 Richfield**

Notes:

Project No.: **n/a**Job No: **8RD0769H**